

Inspection and Testing Log

Project Name: Fairview Platform Rehabilitation

Third Party Contractor: ABC Construction Metra's PM/CM: XYZ Consultants

Inspection / Test	Date Performed	Inspection / Test Location	Inspected / Tested By	Inspection / Test Description	Spec. Section	Results (Pass / Fail)	Comments
Test	2/2/2018	Job Site	A1 Testing	Concrete Test	03300	Pass	None